



NOTE: REMOVE CONTROL JOINT TAB CAREFULLY AS SOON AS STO RFP ADHESIVE HAS SET TO AVOID CRACKS IN THE SYSTEM.

VERTICAL CONTROL JOINTS AT 5.4M CTRS MAX. PREFERABLY ABOVE & BELOW JOINERY JAMB LINE.

SCALE 1:2

STO/CONCRETE BLOCK	STO VENEER WOOD SYSTEM	VWCB 302
	VERTICAL CONTROL JOINT	2020